AMENDMENT OF SOLICITATI	ON/MODIFICATI	ON OF CONTRA	ACT	1. Contract I		Page 1 Of 57
2. Amendment/Modification No.	3. Effective Date	4. Requisition/Purcha	se Req		5. Project No. (I	f applicable)
P00001	2004OCT28	SEE SCHED	ULE			
6. Issued By	Code W56HZV	7. Administered By (If	f other	than Item 6)		Code S1403A
TACOM WARREN		DCMA CHICAGO	DAI DC	220		
AMSTA-AQ-ATBC TERRENCE BROWN (586)574-5373		1523 WEST CENT BLDG 203	RAL RC	DAD		
WARREN, MICHIGAN 48397-5000		ARLINGTON HEIG	HTS I	IL 60004-245	1	
HTTP://CONTRACTING.TACOM.ARMY.MIL EMAIL: BROWNT@TACOM.ARMY.MIL						
EMAIL BROWNIETACOM. ARMI. MIL		SCI	D C	PAS NONE	ADP PT	HQ0339
8. Name And Address Of Contractor (No., Stre	et, City, County, State and	l Zip Code)		9A. Amendmen	nt Of Solicitation I	No.
OSHKOSH TRUCK CORP.						
2307 OREGON STREET P.O. BOX 2566				9B. Dated (See	Item 11)	
OSHKOSH, WI. 54903-2566				104 Madifian	tion Of Contract/C)J N
			X	TUA. Modifica	uon Oi Contract/C	order No.
TYPE BUSINESS: Large Business Perfo	rming in II S			W56HZV-04-D-		
Code 45152 Facility Code				10B. Dated (Se 2004SEP29	ee Item 13)	
	HIS ITEM ONLY APPLI	FS TO AMENDMENTS	S OF SO		IC .	
is extended, is not extended.	ied as set fortil ill item 14.	The nour and date spec	ciffed 10	or receipt of On	iers	
Offers must acknowledge receipt of this amo	endment prior to the hour	and date specified in the	e solicita	ation or as ame	nded by one of the	e following methods:
(a) By completing items 8 and 15, and return	_		-		-	ment on each copy of the
offer submitted; or (c) By separate letter or ACKNOWLEDGMENT TO BE RECEIVE	0					
SPECIFIED MAY RESULT IN REJECTION						
change may be made by telegram or letter, p opening hour and date specified.	provided each telegram or	letter makes reference to	o the so	dicitation and t	his amendment, ai	id is received prior to the
12. Accounting And Appropriation Data (If re	quired)					
NO CHANGE TO OBLIGATION DATA						
KIND MOD CODE: 7	ITEM ONLY APPLIES T				DERS	
A. This Change Order is Issued Pursua		act/Order No. As Descri	bea In		nangos Sot Forth I	n Item 14 Are Made In
The Contract/Order No. In Item 10.				The Ci	langes Set Forth 1	ii iteiii 14 Are Wade III
B. The Above Numbered Contract/Orde Set Forth In Item 14, Pursuant To T			nges (su	ich as changes i	in paying office, a	ppropriation data, etc.)
C. This Supplemental Agreement Is En	tered Into Pursuant To Au	thority Of:				
D. Other (Specify type of modification a	and authority)					
E. IMPORTANT: Contractor is not.	X is required to sign	n this document and retu	ırn		copies to the Issuir	ng Office.
14. Description Of Amendment/Modification (Organized by UCF section	headings, including soli	citation	ı/contract subje	ect matter where fo	easible.)
SEE SECOND PAGE FOR DESCRIPTION						
Contract Expiration Date: 2009SEP30						
Except as provided herein, all terms and condi and effect.	tions of the document refer	renced in item 9A or 10A	A, as he	eretofore chang	ed, remains uncha	nged and in full force
15A. Name And Title Of Signer (Type or print)	16A. Name And	d Title (Of Contracting	Officer (Type or)	orint)
•		GLORIA MCCRA	ACKEN	MY.MIL (586)5		
15B. Contractor/Offeror	15C. Date Signed				,,,=0,,,2,	16C. Date Signed
-	3					
(Signature of person authorized to sign)	_	By(Sign:	ature o	/SIGNED/ f Contracting C	Officer)	2004OCT28
(Digitature of person authorized to sigh)		(Signa	atu1 € 0	. contracting C	,(i)	

Reference No. of Document Being Continued

PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 2 of 57

Name of Offeror or Contractor: OSHKOSH TRUCK CORP.

SECTION A - SUPPLEMENTAL INFORMATION Modification P00001

1. The purpose of Modification P00001 is to add Missing Parts for Reset Repair CLINs for each vehicle system, each ordering year.

2. The following CLINs have been added:

CLI	N 0005-0008	Noun:	Missing	Parts	for	M1070	HET Res	set Re	pair	Ordering	Years	1 ′	through	4
CLI	N 0105-0108	Noun:	Missing	Parts	for	M1074	PLS Res	set Re	pair	Ordering	Years	1 ′	through	4
CLI	N 0115-0118	Noun:	Missing	Parts	for	M1075	CHU Res	set Rep	pair	Ordering	Years	1 ′	through	4
CLI	N 0125-0128	Noun:	Missing	Parts	for	M1075	W/O CHU	J Reset	t Repair	Ordering	Years	1 '	through	4
CLI	N 0135-0138	Noun:	Missing	Parts	for	M1076	Trailer	r Reset	t Repair	Ordering	Years	1 '	through	4
CLI	N 0205-0208	Noun:	Missing	Parts	for	M977 W	/W Rese	et Repa	air	Ordering	Years	1 '	through	4
CLI	N 0215-0218	Noun:	Missing	Parts	for	M977 W	/O W Re	eset Re	epair	Ordering	Years	1 '	through	4
CLI	N 0225-0228	Noun:	Missing	Parts	for	M978 W	/W Rese	et Repa	air	Ordering	Years	1 '	through	4
CLI	N 0235-0238	Noun:	Missing	Parts	for	M978 W	/O W Re	eset Re	epair	Ordering	Years	1 '	through	4
CLI	N 0245-0248	Noun:	Missing	Parts	for	M985 W	/W Rese	et Repa	air	Ordering	Years	1 '	through	4
CLI	N 0255-0258	Noun:	Missing	Parts	for	M985 W	/O W Re	eset Re	epair	Ordering	Years	1 '	through	4
CLI	N 0265-0268	Noun:	Missing	Parts	for	M984A1	Reset	Repair	r	Ordering	Years	1 '	through	4
CLI	N 0275-0278	Noun:	Missing	Parts	for	M1120	Reset F	Repair		Ordering	Years	1 '	through	4
CLI	N 0285-0288	Noun:	Missing	Parts	for	M985E1	Reset	Repair	r	Ordering	Years	1 '	through	4
CLI	N 0295-0298	Noun:	Missing	Parts	for	M983 R	eset Re	epair		Ordering	Years	1 '	through	4
CLI	N 0305-0308	Noun:	Missing	Parts	for	M1977	W/W Res	set Rep	pair	Ordering	Years	1 '	through	4
CLI	N 0315-0318	Noun:	Missing	Parts	for	M1977	W/O W F	Reset 1	Repair	Ordering	Years	1 '	through	4
CLI	N 0325-0328	Noun:	Missing	Parts	for	M977 E	PP Rese	et Repa	air	Ordering	Years	1 '	through	4

- 3. There is no obligation/de-obligation of funds associated with this modification.
- 4. All other terms and conditions shall remain unchanged.

*** END OF NARRATIVE A 001 ***

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 3 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SECTION B - SUPPLIES OR SERVICES AND PRICES/COSTS				
0005	MISSING PARTS FOR M1070 HET RESET REPAIR	EST 309	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 309 \$ 2,000.00				
	NOUN: HET - M1070 RESET Repair Missing Parts First Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0006	MISSING PARTS FOR M1070 HET RESET REPAIR	EST 247	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 4 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	181 247 \$ 2,000.00				
	NOUN: HET - M1070 RESET Repair Missing Parts Second Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0007	MISSING PARTS FOR M1070 HET RESET REPAIR	EST 247	LO	See Range Pricing	ī
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 247 \$ 2,000.00				
	NOUN: HET - M1070 RESET Repair Missing Parts Third Ordering Year Pricing				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 5 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0008	MISSING PARTS FOR M1070 HET RESET REPAIR	EST 247	LO	See Range Pricing	ı
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 247 \$ 2,000.00				
	NOUN: HET - M1070 RESET Repair Missing Parts Fourth Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 6 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
105	MISSING PARTS FOR M1074 PLS RESET REPAIR	EST 51	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: PLS - M1074 RESET Repair Missing Parts First Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS REQUISITION.				
106	MISSING PARTS FOR M1074 PLS RESET REPAIR	EST 33	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 7 **of** 57

1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: PLS - M1074 RESET Repair Missing Parts Second Ordering Year Pricing				
(End of narrative B001)				
Packaging and Marking				
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
MISSING PARTS FOR M1074 PLS RESET REPAIR	EST 33	LO	See Range Pricing	
SECURITY CLASS: Unclassified				
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
NOUN: PLS - M1074 RESET Repair Missing Parts Third Ordering Year Pricing				
	Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M1074 PLS RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00	Enspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL FOST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M1074 PLS RESET REPAIR EST 33 SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00	Packaging and Marking Inspection and Acceptance Inspection: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M1074 PLS RESET REPAIR EST 33 LO SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00	Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M1074 PLS RESET REPAIR EST 33 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 8 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0108	MISSING PARTS FOR M1074 PLS RESET REPAIR	EST 33	LO	See Range Pricing	ī
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: PLS - M1074 RESET Repair Missing Parts Fourth Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 9 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0115	MISSING PARTS FOR M1075 W/CHU RESET REPAIR	EST 252	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 252 \$ 2,000.00				
	NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
	MISSING PARTS FOR M1075 W/CHU RESET REPAIR	EST 215	LO	See Range Pricing	
0116					

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 10 of 57

Range Quantities	ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
(End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION Origin ACCEPTANCE: Origin FOB FOINT: Origin ACCEPTANCE: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP TO) WILL RE FURNISHED PRIOR TO THE SCHEDULD DELIVERY DATE FOR ITEMS REQUISITION. PROUISITION. MISSING PARTS FOR M1075 W/CHU RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 181 215 \$ 2,000.00		FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00				
Eackaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. 117 MISSING FARTS FOR MI075 W/CHU RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 181 215 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 W/CHU RESET Repair Missing Parts						
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FUNNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. MISSING PARTS FOR MI075 W/CHU RESET REPAIR EST 215 LO See Range Pricing Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts		(End of narrative B001)				
INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 117 MISSING PARTS FOR M1075 W/CHU RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts		Packaging and Marking				
SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. MISSING PARTS FOR M1075 W/CHU RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts		INSPECTION: Origin ACCEPTANCE: Origin				
Range Quantities FROM TO		SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS				
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts	117	MISSING PARTS FOR M1075 W/CHU RESET REPAIR	EST 215	LO	See Range Pricing	Ţ
FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00 NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts		SECURITY CLASS: Unclassified				
		FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 11 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
118	MISSING PARTS FOR M1075 W/CHU RESET REPAIR	EST 215	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 215 \$ 2,000.00				
	NOUN: PLS - M1075 w/CHU RESET Repair Missing Parts Fourth Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 12 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0125	MISSING PARTS FOR M1075 W/O CHU RESET REPAIR	EST 1	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: PLS - M1075 w/o CHU RESET Repair Missing Parts First Ordering Year Pricing	\$			
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0126	MISSING PARTS FOR M1075 W/O CHU RESET REPAIR	EST 1	LO	See Range Pricing	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 13 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: PLS - M1075 w/o CHU RESET Repair Missing Parts	3			
	Second Ordering Year Pricing				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS REQUISITION.				
	100000000000000000000000000000000000000				
0127	MAGGANG DADEG FOR MAGES W/O GWY DEGET DEDATE	EST 1		See Range Pricing	
J12 <i>1</i>	MISSING PARTS FOR M1075 W/O CHU RESET REPAIR	F21 I	LO	see Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00 31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: PLS - M1075 w/o CHU RESET Repair Missing Parts Third Ordering Year Pricing	3			

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 14 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS				
1128	REQUISITION. MISSING PARTS FOR M1075 W/O CHU RESET REPAIR SECURITY CLASS: Unclassified	EST 1	LO	See Range Pricing	
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: PLS - M1075 w/o CHU RESET Repair Missing Parts Fourth Ordering Year Pricing	s			
	(End of narrative B001)				
	Packaging and Marking				

Reference No. of Document Being Continued

MOD/AMD P00001

Page 15 of 57

PIIN/SIIN W56HZV-04-D-0322

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0135	MISSING PARTS FOR M1076 TRAILER RESET REPAIR	EST 240	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 500.00 31 90 \$ 500.00 91 180 \$ 500.00 181 240 \$ 500.00				
	NOUN: PLS - M1076 Trailer RESET Repair Missing Part: First Ordering Year	5			
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 16 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0136	MISSING PARTS FOR M1076 TRAILER RESET REPAIR	EST 203	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 500.00 31 90 \$ 500.00 91 180 \$ 500.00 181 203 \$ 500.00				
	NOUN: PLS - M1076 Trailer RESET Repair Missing Parts Second Ordering Year	3			
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0137	MISSING PARTS FOR M1076 TRAILER RESET REPAIR	EST 203	LO	See Range Pricing	r
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 500.00 31 90 \$ 500.00 91 180 \$ 500.00 181 203 \$ 500.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 17 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	NOUN: PLS - M1076 Trailer RESET Repair Missing Parts Third Ordering Year	3			
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0138	MISSING PARTS FOR M1076 TRAILER RESET REPAIR	EST 203	LO	See Range Pricing	ı
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 500.00 31 90 \$ 500.00 91 180 \$ 500.00 181 203 \$ 500.00				
	NOUN: PLS - M1076 Trailer RESET Repair Missing Parts Fourth Ordering Year	3			
	(End of narrative B001)				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 18 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0205	MISSING PARTS FOR M977 WW RESET REPAIR	EST 9	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE 1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 W/W RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 19 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0206	MISSING PARTS FOR M977 WW RESET REPAIR	EST 8	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE 1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 W/W RESET Repair Missing Parts Second Ordering Year				
	Second Ordering real				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
	REQUISITION.				
207	MICCING DADEC FOR MOTT WILL DECEM DEDAID	EST 8	LO	See Range Pricing	
207	MISSING PARTS FOR M977 WW RESET REPAIR	FOI 0	LO	see Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	I and the second	I	1	i l	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 20 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 W/W RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0208	MISSING PARTS FOR M977 WW RESET REPAIR	EST 8	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00				
	31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 W/W RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 21 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001) Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0215	MISSING PARTS FOR M977 WOW RESET REPAIR	EST 12	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 WOW RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 22 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
216	MISSING PARTS FOR M977 WOW RESET REPAIR	EST 10	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 WOW RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
217	MISSING PARTS FOR M977 WOW RESET REPAIR	EST 10	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	1	l	1	1	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 23 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 WOW RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0218	MISSING PARTS FOR M977 WOW RESET REPAIR	EST 10	LO	See Range Pricing	r.
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 WOW RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 24 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0225	MISSING PARTS FOR M978 WW RESET REPAIR	EST 13	LO	See Range Pricing	•
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 W/W RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 25 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
226	MISSING PARTS FOR M978 WW RESET REPAIR	EST 12	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 W/W RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
)227	MISSING PARTS FOR M978 WW RESET REPAIR	EST 12	LO	See Range Pricing	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 26 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 W/W RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0228	MISSING PARTS FOR M978 WW RESET REPAIR	EST 12	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 W/W RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 27 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
1235	MISSING PARTS FOR M978 WOW RESET REPAIR	EST 20	LO	See Range Pricing	ī
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 WOW RESET Repair Missing Parts First Ordering Year				
	(Turk of many the 2001)				
	(End of narrative B001)				
	Packaging and Marking				
	FOB POINT:				
	SHIP TO: PARCEL POST ADDRESS				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 28 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
236	MISSING PARTS FOR M978 WOW RESET REPAIR	EST 17	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 WOW RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	FOB POINT:				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
237	MISSING PARTS FOR M978 WOW RESET REPAIR	EST 17	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 29 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 WOW RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	FOB POINT: SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0238	MISSING PARTS FOR M978 WOW RESET REPAIR	EST 17	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M978 WOW RESET Repair Missing Parts Fourth Ordering Year				
	(End of narrative B001)				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 30 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking				
	FOB POINT:				
	SHIP TO: <u>PARCEL POST ADDRESS</u> (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS				
	REQUISITION.				
0245	MISSING PARTS FOR M985 WW RESET REPAIR	EST 11	LO	See Range Pricing	ı
	SECURITY CLASS: Unclassified				
	BEOMIT CHIEF ONCIUDITIES				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00 31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M985 W/W RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
	REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 31 **of** 57

			UNIT PRICE	AMOUNT
MISSING PARTS FOR M985 WW RESET REPAIR	EST 10	LO	See Range Pricing	ī
SECURITY CLASS: Unclassified				
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Second Ordering Year				
(End of narrative B001)				
Packaging and Marking				
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
FOB POINT: Origin				
SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
MISSING PARTS FOR M985 WW RESET REPAIR	EST 10	LO	See Range Pricing	
SECURITY CLASS: Unclassified				
Range Ouantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00	Range Quantities	Range Cuantities FROM TO UNIT_PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin SHIP TO: PARCEL_POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR MISSING PARTS FOR M985 WW RESET REPAIR EST 10 LO SECURITY CLASS: Unclassified Range Cuantities FROM TO UNIT_PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 181 200 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMIT - M985 W/W RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHEPPING INSTRUCTIONS FOR CONSIGNEE (SHIP TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITHEN REQUISITION. MISSING PARTS FOR M985 WM RESET REPAIR EST 10 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO HINT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00 31 90 \$ 2,000.00

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 32 **of** 57

NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Third Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
MISSING PARTS FOR M985 WW RESET REPAIR	EST 10	LO	See Range Pricing	
SECURITY CLASS: Unclassified				
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Fourth Ordering Year				
(End of narrative B001)				
	ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Fourth Ordering Year	ITEMS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR EST 10 SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Fourth Ordering Year	ITEMS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR EST 10 LO SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Fourth Ordering Year	ITEMS REQUISITION. MISSING PARTS FOR M985 WW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 W/W RESET Repair Missing Parts Fourth Ordering Year

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 33 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	GWID TO DARGEY DOGT ADDRESS				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
	REQUISITION.				
0255	MISSING PARTS FOR M985 WOW RESET REPAIR	EST 23	LO	See Range Pricing	ı
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	101 200 \$ 2,000.00				
	NOUN: HEMTT - M985 WOW RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	100 TOTAL OFFICE				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
		1	1		
	REQUISITION.				
	REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 34 of 57

SECURITY CLASS: Unclassified Range Quantities PROM TO UNIT PRICE 1 30 8 2,000.00 31 180 8 2,000.00 31 180 8 2,000.00 31 180 8 2,000.00 31 180 8 2,000.00 31 180 8 2,000.00 NOUN: HEMTT - M985 WOW RESET Regair Missing Parts Second Ordering Tear (End of narrative BOO1) Rankaging and Marking Inspection and Acceptance TMSSECTION: Origin ACCEPTANCE: Origin FOR POINT: Origin SHIPPIND INSTRUCTIONS FOR CONSIGNER (SHIPPIND INSTRUCTIONS FOR CONSIGNER (SHIPPIND INSTRUCTIONS FOR CONSIGNER (SHIPPIND REQUIRED UNDER THIS SEQUENCE OF SERVICE AND SERVED FROM TYPE SCHEDULED PRIVERY OFF FOR TITHES REQUIRED UNDER THIS SEQUENCE OF SERVED FROM SERVED FROM SEQUENCE CLASS: Unclassified Mange Quantities FROM TO UNIT PRICE	AMOUNT	UNIT PRICE	UNIT	QUANTITY	SUPPLIES/SERVICES	ITEM NO
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HERTT - M985 MUN RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Endbaging and Marking Lagsciicn and Acceptance INSPECTION: Origin SHIP TO: PARCEL BOST ADDRESS (Y00000) SHIPTING INSTRUCTIONS FOR CONSIGNEE (Y00000) SHIPTING INSTRUCTIONS FOR CONSIGNEE (TO THE SCHEDULED DELIVERY DATE FOR TIMES REQUISITION. MISSING PARTS FOR M985 NOW RESET REPAIR EST 21 LO See Range Pricing SRCURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Range Cuantities FROM TR UNIT_PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HENTT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB FOINT: Origin SHIP TO: PARCEL FOST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP-TO) WILL BE FUNDISHED PRICE TO THE SCHEDULED DELIVERY DATE FOR ITTMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 NOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Countities FROM TO UNIT_PRICE						
Range Countities PROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 181 200 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMIT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00001) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP-TO) WILL BE FURNISHED FROR ITEMS REQUISED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE	ng	See Range Pricing	LO	EST 21	MISSING PARTS FOR M985 WOW RESET REPAIR)256
Range Cuantities FROM TO INIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 NOUN: HEMTT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOR POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FUNNISHED PRIOR ITEMS REQUISED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Cuantities FROM TO INIT PRICE						
FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 NON RESET Repair Missing Parts Second Ordering Year (End of narrative H001) Rackaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOR POINT: Origin ACCEPTANCE: Origin FOR POINT: Origin ACCEPTANCE: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 NOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					SECURITY CLASS: Unclassified	
FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 NON RESET Repair Missing Parts Second Ordering Year (End of narrative H001) Rackaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOR POINT: Origin ACCEPTANCE: Origin FOR POINT: Origin ACCEPTANCE: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 NOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
1 30 \$ 2,000.00 31 90 \$ 2,000.00 181 200 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: Packet POST ADDRESS (Y00000) SHIPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. MISSING PARTS FOR M985 NOW RESET REPAIR EST 21 LO See Range Pricins SECURITY CLASS: Unclassified Range_Quantities FROM TO UNIT_ERICE						
31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMIT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin ACCEPTANCE: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 NOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT_PRICE						
91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMIT - M985 WON RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL FOST ADDRESS (Y0000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL RE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. 257 MISSING PARTS FOR M985 WON RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT_PRICE						
NOUN: HEMTT - M985 WOW RESET Repair Missing Parts Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL FOST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (Y00000) TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUISITION. MISSING PARTS FOR M985 WON RESET REPAIR SECURITY CLASS: Unclassified Range_Quantities FROM TO UNIT_FRICE						
Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 NOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					181 200 \$ 2,000.00	
Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 MOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Second Ordering Year (End of narrative B001) Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNER (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					NOIN: HEMTT - M985 WOW RESET Repair Missing Parts	
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. PER AUGUSTION. MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					(End of narrative B001)	
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					Packaging and Marking	
INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					Inspection and Acceptance	
SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					INSPECTION: Origin ACCEPTANCE: Origin	
(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					FOB POINT: Origin	
(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR EST 21 LO See Range Pricing SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE					SHIP TO: PARCEL POST ADDRESS	
TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION. MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
ITEMS REQUIRED UNDER THIS REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
REQUISITION. 257 MISSING PARTS FOR M985 WOW RESET REPAIR SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE						
SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE		Coo Bongo Driging	T O	ECT 21	MICCING DADEC FOR MOSE WOW DECET DEDAIL	257
Range Quantities FROM TO UNIT PRICE	119	See Range Pricing	LO	F21 Z1	MISSING PARTS FOR MOOS WOW RESEL REPAIR	.57
Range Quantities FROM TO UNIT PRICE					SECURITY CLASS: Unclassified	
FROM TO UNIT PRICE						
FROM TO UNIT PRICE					Range Quantities	
1 30 \$ 2,000.00						
31 90 \$ 2,000.00						
91 180 \$ 2,000.00 181 200 \$ 2,000.00						
					255	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 35 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	NOUN: HEMTT - M985 WOW RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0258	MISSING PARTS FOR M985 WOW RESET REPAIR	EST 21	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M985 WOW RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 36 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0265	MISSING PARTS FOR M984A1 RESET REPAIR	EST 18	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M984Al RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 37 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	ITEMS REQUIRED UNDER THIS REQUISITION.				
)266	MISSING PARTS FOR M984A1 RESET REPAIR	EST 16	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M984A1 RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0267	MISSING PARTS FOR M984A1 RESET REPAIR	EST 16	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 38 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M984Al RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0268	MISSING PARTS FOR M984A1 RESET REPAIR	EST 16	LO	See Range Pricing	ī
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M984A1 RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 39 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0275	MISSING PARTS FOR M1120 RESET REPAIR	EST 14	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1120 RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	(Bid of idiractive boot)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	SHIP TO: PARCEL POST ADDRESS				

Reference No. of Document Being Continued

PIIN/SIIN W56HZV-04-D-0322 MOD/AMD P00001

Page 40 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE AMOUNT
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.			
276	MISSING PARTS FOR M1120 RESET REPAIR	EST 10	LO	See Range Pricing
	SECURITY CLASS: Unclassified			
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00			
	NOUN: HEMTT - M1120 RESET Repair Missing Parts Second Ordering Year			
	(End of narrative B001)			
	Packaging and Marking			
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin			
	FOB POINT: Origin			
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.			
0277	MISSING PARTS FOR M1120 RESET REPAIR	EST 10	LO	See Range Pricing
	SECURITY CLASS: Unclassified			

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 41 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1120 RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0278	MISSING PARTS FOR M1120 RESET REPAIR	EST 10	LO	See Range Pricing	Ţ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1120 RESET Repair Missing Parts Fourth Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 42 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0285	MISSING PARTS FOR M985E1 RESET REPAIR	EST 2	LO	See Range Pricing	1
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M985E1 RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				

Reference No. of Document Being Continued

MOD/AMD P00001

Page 43 **of** 57 CONTINUATION SHEET PIIN/SIIN W56HZV-04-D-0322

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
286	MISSING PARTS FOR M985E1 RESET REPAIR	EST 1	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M985E1 RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
		EST 1	LO	See Range Pricing	

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 44 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE 1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	\$ 2,000.00				
	NOUN: HEMTT - M985E1 RESET Repair Missing Parts				
	Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS REQUISITION.				
	Algorotitow.				
0288	MISSING PARTS FOR M985E1 RESET REPAIR	EST 1	LO	See Range Pricing	
	CDCVD TRV CV 2004 Vand and 6144				
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00 31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M985E1 RESET Repair Missing Parts				
	Fourth Ordering Year				
			<u></u>		

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 45 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001) Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
295	MISSING PARTS FOR M983 RESET REPAIR	EST 2	LO	See Range Pricing	
	Range Quantities				
	NOUN: HEMTT - M983 RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 46 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0296	MISSING PARTS FOR M983 RESET REPAIR	EST 1	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M983 RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

Page 47 of 57

MOD/AMD P00001

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0297	MISSING PARTS FOR M983 RESET REPAIR	EST 1	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	SECURITY CLASS: Unclassified				
	Range Quantities				
	FROM TO UNIT PRICE 1 30 \$ 2,000.00				
	31 90 \$ 2,000.00 91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M983 RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS REQUISITION.				
0298	MISSING PARTS FOR M983 RESET REPAIR	EST 1	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00 91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 48 of 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
TEM NO	NOUN: HEMTT - M983 RESET Repair Missing Parts Fourth Ordering Year (End of narrative B001)	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Turnetian and Assertance				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
305	MISSING PARTS FOR M1977 WW RESET REPAIR	EST 9	LO	See Range Pricing	ſ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts First Ordering Year				
	(End of narrative B001)				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 49 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
	REQUISITION.				
0306	MISSING PARTS FOR M1977 WW RESET REPAIR	EST 7	LO	See Range Pricing	,
	SECURITY CLASS: Unclassified				
	Dango Overtitiss				
	Range Quantities FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	91 180 \$ 2,000.00				
	181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS				
	(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE				
	(SHIP-TO) WILL BE FURNISHED PRIOR				
	TO THE SCHEDULED DELIVERY DATE FOR				
	ITEMS REQUIRED UNDER THIS				
	REQUISITION.				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 50 **of** 57

### SECURITY CLASS: Unclassified Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year Third Order	LO	See Range Pricing	
Range Quantities FROM TO	LO	See Range Pricing	
Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
Range Ouantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
91 180 \$ 2,000.00 181 200 \$ 2,000.00 NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Third Ordering Year			
Third Ordering Year			
(End of variation 2001)			
(End of requestion 2001)			
(End of nameting DOOL)			
(End of remeting DOOL)		1	
(End of narrative B001)			
Packaging and Marking			
Inspection and Acceptance			
INSPECTION: Origin ACCEPTANCE: Origin			
FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS			
(Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE			
(SHIP-TO) WILL BE FURNISHED PRIOR			
TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS			
REQUISITION.			
0308 <u>MISSING PARTS FOR M1977 WW RESET REPAIR</u> EST 7	' LO	See Range Pricing	Į.
SECURITY CLASS: Unclassified			
Range Quantities			
FROM TO UNIT PRICE 1 30 \$ 2,000.00			
31 90 \$ 2,000.00			
91 180 \$ 2,000.00 181 200 \$ 2,000.00			
, 2,000.00			

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 51 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	NOUN: HEMTT - M1977 W/W RESET Repair Missing Parts Fourth Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0315	MISSING PARTS FOR M1977 WOW RESET REPAIR	EST 30	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 WOW RESET Repair Missing Parts First Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 52 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0316	MISSING PARTS FOR M1977 WOW RESET REPAIR	EST 21	LO	See Range Pricing	ı
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 WOW RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR				

Reference No. of Document Being Continued

Page 53 **of** 57

MOD/AMD P00001 PIIN/SIIN W56HZV-04-D-0322

Name of Offeror or	Contractor	OGITIZOGIT	mprior	CODD	

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	ITEMS REQUIRED UNDER THIS REQUISITION.				
317	MISSING PARTS FOR M1977 WOW RESET REPAIR	EST 21	LO	See Range Pricing	ţ
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 WOW RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
318	MISSING PARTS FOR M1977 WOW RESET REPAIR	EST 21	LO	See Range Pricing	•
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 54 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M1977 WOW RESET Repair Missing Parts Fourth Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0325	MISSING PARTS FOR M977 EPP RESET REPAIR	EST 1	LO	See Range Pricing	;
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 EPP RESET Repair Missing Parts First Ordering Year				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 55 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
0326	MISSING PARTS FOR M977 EPP RESET REPAIR	EST 1	LO	See Range Pricing	ş
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 EPP RESET Repair Missing Parts Second Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				

Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-D-0322

MOD/AMD P00001

Page 56 **of** 57

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
327	MISSING PARTS FOR M977 EPP RESET REPAIR	EST 1	LO	See Range Pricing	
	SECURITY CLASS: Unclassified				
	Range Quantities FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 EPP RESET Repair Missing Parts Third Ordering Year				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				
1328	MISSING PARTS FOR M977 EPP RESET REPAIR	EST 1	LO	See Range Pricing	

Reference No. of Document Being Continued

Page 57 **of** 57

PIIN/SIIN W56HZV-04-D-0322 MOD/AMD P00001

Name of Off	on on Contractors			J 100001	
Name of Offer ITEM NO	or or Contractor: OSHKOSH TRUCK CORP. SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SECURITY CLASS: Unclassified	QUIII III		STATE I MICE	111.130111
	DECORTIT CHOOP UNCLASSIFIED				
	Range Quantities				
	FROM TO UNIT PRICE				
	1 30 \$ 2,000.00				
	31 90 \$ 2,000.00				
	FROM TO UNIT PRICE 1 30 \$ 2,000.00 31 90 \$ 2,000.00 91 180 \$ 2,000.00 181 200 \$ 2,000.00				
	NOUN: HEMTT - M977 EPP RESET Repair Missing Parts Fourth Ordering Year				
	J				
	(End of narrative B001)				
	Packaging and Marking				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	FOB POINT: Origin				
	SHIP TO: PARCEL POST ADDRESS (Y00000) SHIPPING INSTRUCTIONS FOR CONSIGNEE (SHIP-TO) WILL BE FURNISHED PRIOR TO THE SCHEDULED DELIVERY DATE FOR ITEMS REQUIRED UNDER THIS REQUISITION.				